


2CZ140CMS1P (2CZ140CS1P) 型快恢复二极管技术参数说明

参数	型号	2CZ140CMS1P (2CZ140CS1P) (SMA)	单位
V_{RRM}		400	V
I_F		1.0	A
I_{FSM}		30	A
T_j / T_{STG}		-55~150	°C
$V_F @ I=1A$		≤1.7	V
I_{R1} @ $V_{RRM} @ T_A=25^{\circ}C$		≤5	μ A
I_{R2} @ $V_{RRM} @ T_A=100^{\circ}C$		≤100	μ A
t_{rr} @ $I_F=0.5A, I_R=1.0A,$ $I_{rr}=0.25A$		≤150	ns

SMA 封装外形图：inch (mm)



备注：色带处标注为阴极